

Last updated April 01, 2013.

Copyright 2006-2013 Michael P. Murray & Mike's Clock Clinic

The chart below is an illustration of when Hermle started 1975 and then stopped 1990 using nickel plated pivots instead of the traditional hard polished steel.

I place this on the Internet so that repair persons can decide whether or not to overhaul the movement or simply replace. If you see any damage to any pivot within the years 1975 to 1989, you will probably better serve the customer and yourself by replacing the movement.

If anyone has any data on Urgos, Jauch, Kieninger, I would very much appreciate that information and will gladly add it to the chart.

Manufacturer	Model #	Year Made	Plated	Non Plated
Hermle		1975	Yes	
Hermle	141-080	1974		Non
Hermle		1975 to 1989	Yes	
Seth Thomas (Hermle movement)	A208-007	1975	Yes	
Hermle Date Codes A = 1988; B = 1989			Yes	
Hermle Date Codes C = 1990; D = 1991, Etc.				Non

A service from, E-mail address: Mike@atmos-man.com  
Mike Murray Founder of Clocksmiths

A specialist in Atmos and 400-day clock repair.  
Also, I overhaul most plug in electric clocks and motors.  
In continuous horological service since 04/01/1982.

Mike's Clock Clinic Memberships: Clocksmiths & NAWCC  
1600 Maryland Avenue  
Myrtle Point, OR 97458-1508

Phone: 541-559-1090 or 877-286-6762

My main Web site is located at "<http://www.atmosman.com/>"

Main FTP site is located at:  
"<http://home.earthlink.net/~atmosman/earthftp.html>"

Copyright 2006-2013 Michael P. Murray & Mike's Clock Clinic